

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program May 29, 2008

Reviewed

Mine Name: Eureka Rock	Permit Number: S0230094 Inspection Date: March 13, 2008 Time: 1:00 am		
Operator Name: Eureka Rock LLC			
Inspector(s): L Heppler, T Munson			
Other Participants: None	Mine Status: ACT		
Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, Soils Revegetation 			

Bond Renewal Date: 12-20-2009 Bond Amount: \$15,300 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection

Inspection Summary: Every effort should be made to salvage topsoil from the site prior to mining or constuction.

Photos were taken to document site conditions.

Conclusions and Recommendations: OGM to continue annual inspections and monitor the site when in the area.

22 06 2 11 John 1

LAH:pb cc: Ben McInnes Attach - GIS File Name and Path Inspection March 13, 2008 Page 2 of 2 M/023/0094

Photo Taken 03-13-08

